

Iron N^o. 14672

Report of Survey for Repairs of Engines and Boilers.

No. _____
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey July 29 1875
150 on the Cocks and Piping of S.S. Goston Tons 1334
Owners J. Hall & Co. Port belonging to London Classed 100 AT
Years assigned. Character in Register Book.

Diameter of Cylinder 24" 54" Engines made at Brest-Hautlepool When made 1841
Length of Stroke 36" Pressure of Steam _____ By whom made Blair & Co.
Nominal Horse Power 120

Particulars of Repairs and Examination

On examination the cocks and piping in connection with the machinery and boilers of this vessel were found to be so arranged that by an act of carelessness or neglect water could not be run from the sea into the bilge

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }
(Travelling Expenses, if any, £ _____)

James Bain
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute 18

End 18. 8. 75



© 2019

Lloyd's Register
Foundation

IRON 462 - 0040