

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 11146** Survey held at Sunderland Date, first Survey June 12th Last Survey June 15th 18 75

269 on the Sem. str. Nordstjernan Master M. E. Drescher

Tonnage 1262 ¹²⁶² built at Sunderland When built 1873. (2 mo)

By whom built Bartram

Owners Norden St. Sh. Co.

Port belonging to Copenhagen

Destined Voyage

If Surveyed Afloat or in Dry Dock

South Graving Dock

Last Survey, No. 13052.

Port Sunderland

Classed

Years assigned.

Character in Register Book.

90 A. 1

4.73

REPAIRS, OR EXAMINATION AS PER RULE

Annual Survey

The Keel and Bottom cleaned and payed with three coats of Patent Composition (Swedish) each compartment examined; that under Engine found secure &c in good condition; Renewed one short length of upper Deck (damaged) with yellow Pine and Caulked the Deck throughout.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Keelsons

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

When put on

Paint

When put on

Paint

When put on

Paint

When put on

Paint

The Amount of Entry Fee

Special

Certificate (if required)

(Travelling Expenses, if any, &c.)

Committee's Minute

Character assigned

received by me,

23rd June 1875

25th June 1875

1875

1875

1875

1875

1875

1875

1875

1875

Joseph A. Allen

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 462-0048