

Iron N^o * 14708

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Reid 13.8.75)
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 25th June 1875
125 on the Cocks and piping of S.S. Camilla 956 Tons
Owners Gen. M. Ship Coy Port belonging to London Classified _____ Years assigned _____ Character in Register Book. 100 AI

Diameter of Cylinder 26" & 51" Engines made at Newcastle When made 1866
Length of Stroke 30" Pressure of Steam 2 By whom made Hawthorn's Compounded by Vic. Beck Engine Works
Nominal Horse Power 160 London

Particulars of Repairs and Examination

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)
On examination the Cocks and piping in connection with the Machinery and Boilers of this vessel were found to be so arranged that by an act of carelessness or neglect water could be run from the sea into the bilge. Non return valves have been fitted to the donkey suction pipe so as to prevent the possibility of such an accident.

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }
(Travelling Expenses, if any, £)

Committee's Minute

18

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Ent 18. 8. 75



© 2019

Lloyd's Register
Foundation

IRON462-0089