

*Iron No 14717*

# Report of Survey for Repairs of Engines and Boilers.

(Rec'd 16.8.75)

No. \_\_\_\_\_

No. in  
Reg. Book.

Survey held at

*London*

Date, first Survey

Last Survey

*June 17 1875*

*196*

on the *Cocks and Piping of S. S. Hawthorns*

*699* Tons

Owners

*S. Strick & Son*

Port belonging to

*London*

Classed

Years  
assigned.

Character in Register Book.

*A 1*

Diameter of Cylinder *25" x 48"*

Length of Stroke *30"*

Pressure of Steam *15*

Nominal Horse Power *99*

Engines made at

*Newcastle*

When made

*1861*

*Compound 1873*

By whom made

*Hawthorne Comp. by Lic. Dock Engine Works. London*

YEAR.

## Particulars of Repairs and Examination

*On examination the Cocks and piping in  
Connection with the Boilers and Machinery of this vessel  
were found to be so arranged, that, by an act of  
carelessness or neglect water could not be run from the  
sea into the bilge.*

(Condition of Engines and Boilers, and subsequent repairs and examinations, to be clearly stated.)

The Amount of Fee ... £ : : received by me, }  
Certificate (if required) ... £ : : 187 }

(Travelling Expenses, if any, £ )

Committee's Minute

18

*Oct 18 8.75*

*Ames Bain*  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

1R0W462-0103

(The Surveyors are requested not to write on or below the space for Committee's Minute.)