

REPORT of SURVEY for REPAIRS, &c.

14 7/4

34.876

Recd 9/7/5

No. in Reg. Book. 491 No. 11283 Survey held at London Date, first Survey 2nd July Last Survey July 5th 1875
 on the Iron Screw Steamer Charles Capper Master Wm Wilson
 Tonnage 479.761 built at Newcastle When built 1864 *with mth*
 By whom built Palmer Owners E. Noble
 Port belonging to London Destined Voyage Tyne, River
 If Surveyed Afloat or in Dry Dock Commercial dry dock
 Last Survey, No. 11283 Port Lron Classified 85.A.1. *S.S. No 3*
 REPAIRS, OR EXAMINATION AS PER RULE S.S. No 1,

Lifted a strake of Ceiling at the bilge fore and aft on both sides, opened the Man hole doors in the Tanks, the hatches and linings in the Engine Room. Cleaned her out, examined the Cement, and asphalt, found it in good condition and adhering satisfactorily. Repaired it where necessary in local places with Cement. Cleaned the bottom, and recoated it, also the sides of the Vessel. Examined her inside and outside throughout or as far as practicable. - Lifted the Chain Cables from the lockers, ranged them on deck, they proved sufficient in size and in quantity also. - Overhauled the windlass which apparently has been recently relined. See reports. -

Present Condition of the					
Decks	good	Freeboards	Rivets where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the deck
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 No. 18. 2 No.
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder efficient	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	When put on	Standing & Running Rigging	"
Engine Room Skylights	good	Caulking of	good	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	good	Hatches	good
General Observations, Opinion as to Class, &c.					

She is now in good condition, and the Rules having been complied with, I am of opinion she is entitled to remain as class'd. 85.A.1. and to be marked in the Regⁿ S.S. No 1. 1875.

Samuel Wilson

The Amount of Entry Fee ... £ 2 : 2 :
 Special ... £ 2 : 2 :
 Certificate (if required) ... £ - : 5 :
 (Travelling Expenses, if any, £)
 Committee's Minute 16th July 1875
 Character assigned 85.A.1.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON462-0173