

14783

REPORT of SURVEY for REPAIRS, &c.

No. 3/8/75

No. in Reg. Book. **No. 4394** Survey held at Hull Date, first Survey 28th June Last Survey 7th July 1875
on the Iron Steamer "Don Antonio" Master Hilala
Tonnage 1441 built at Glasgow When built 1860
By whom built Hill Owners Bailey & Co
Port belonging to Lisbon Destined Voyage Lisbon
If Surveyed Afloat or in Dry Dock On Humphry Hanon Ship-way & Afloat in Albert St.

Last Survey, No. 12719 Port Iron Classed 100 A 1
REPAIRS, OR EXAMINATION AS PER RULE Survey No. 2 S.S. Hul No. 1-70

Cause of Repairs to be clearly stated.

Ceiling removed in accordance with the rules (Accepting in the Throstship Coal bunker which will be removed for Ammunition on the vessels return to this Country) and the plating outside and inside from close ceiling upwards cleaned & painted. Cement examined & repaired. Windlass overhauled & repaired. Chain cables on deck. Ceiling when removed pe-laid or renewed as found necessary. Boiler cleaned & Engines thoroughly overhauled.

Present Condition of the

Decks	<u>Good</u>	Treenails <u>with</u>	<u>Good</u>	Windlass and Capstan <u>good</u>	<u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>4 in No</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>Inspection</u>	
Planksheers		Keelsons		Sails <u>good & sufficient</u>	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B / 3 C / 2 D</u>	
Topsides		Ceiling		Cables <u>300 fms P/4</u>	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper When put on		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>for</u>	Cargo and Main Hatchways <u>for</u> Hatches <u>for</u>			
General Observations, Opinion as to Class, &c.					

Is now in good condition and eligible in my opinion to remain as classed 100 A 1 & be marked S.S. Hul No. 2-75

The Amount of Entry Fee ... £ 3 : - : - received by me, 188
Special ... £ 4 : 4 : - 11th July 1875
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)
Committee's Minute 3rd August 1875
Character assigned 100 A

Mr Davidson
Surveyor to Lloyd's Register of British and Foreign Shipping.