

14869. 377846

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey _____ Last Survey July 13th 1875

418 on the SS Windsor Castle Master Hewitt

TONNAGE under Tonnage Deck <u>2623</u>	Built at <u>Glasgow</u>	When built <u>1872</u>	YEAR. MONTH.
Ditto of Spar Deck, or Awning Deck	Owners <u>S Currie</u>	Port belonging to <u>London</u>	
Ditto of Poop, or Raised Qr. Dk.	Residence _____	Destined Voyage _____	
Ditto of Houses on Deck	By whom built <u>Napier</u>		
Ditto of Forecastle	If Surveyed Afloat or in Dry Dock <u>dry dock</u>		
Gross Tonnage <u>2672</u>			
Crew Space, as per Rule			
Register Tonnage, cut on Beam			
Engine Room			
Reg. Tons as St'mer, cut on Bm. <u>1732</u>			

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. 100 A1 475 Character in Register Book. _____

Last Survey, No. 14483 Port Iron Classed 100 A1 475

REPAIRS, OR EXAMINATION AS PER RULE

at the present time owing to damage
Renewed one outside plate above the bilges
on the starboard side. Bottom Scraped Painted & Coated

Present Condition of the					
Decks	<u>Good</u>	Freemasts	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stenson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained
Planksheers	"	Keelsons	"	"	Sails
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of 3 <u>200 lbs</u>
Topsides	"	Ceiling	"	"	Cables
Wales	"	Rudder	"	"	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper <u>Painted</u> When put on <u>new</u>	"	"	Standing & Running Rigging
Engine Room Skylights	<u>Good</u>	Caulking of	"	"	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>	"	Hatches
Scuppers	<u>Good</u>				
General Observations, Opinion as to Class, &c.					

She is now in an efficient state
of repair and entitled to remain as classed

Leahouse Martindale

The Amount of Entry Fee ... £ ... : : } received by me, Hewitt
26.7.75 Special ... £ 2 : 2 : } 28/7/1875
Certificate (if required) ... £ : 5 : }
(Travelling Expenses, if any, £ _____)
Committee's Minute 30th July 18 75
Character assigned 100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.