

Iron No. 14888

# Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_  
No. in Reg. Book. Survey held at London Date, first Survey \_\_\_\_\_ Last Survey 21<sup>st</sup> July 1875  
698 on the Cock & Piping of S.S. Mary Nixon Tons 758  
Owners J. Nixon Port belonging to Newcastle Classified \_\_\_\_\_ Years assigned \_\_\_\_\_ Character in Register Book. A1

Diameter of Cylinder 26 x 51 Engines made at Newcastle When made 1865  
Length of Stroke 30 Pressure of Steam 2 By whom made W. L. Compounded by Vic Dock Engine Works  
Nominal Horse Power 100 London

## Particulars of Repairs and Examination

On examination the cocks and piping in connection with the machinery and boilers of this vessel were found to be so arranged that by an act of carelessness or neglect water could not be run from the sea into the bilge

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write on or below the space for Committee's Minute).

The Amount of Fee ... £ : : received by me, }  
Certificate (if required) ... £ : : 187 }  
(Travelling Expenses, if any, £ )  
Committee's Minute 18  
Ent 18. 8 75

Ames Bain  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

