

ANNUAL SURVEYS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Aug 6 Last Survey Aug 6 1875
 on the Iron Screw Steamer Acton Master Young
 Tonnage 1066, 1646 Built at Newcastle When built 1874
 By whom built Mitchell Owners E. H. Watts
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Mill Wall dry dock

Last Survey, No. 13386 Port of Iron Classed 100. A. 1.

Present Condition of the
 Decks good Treennails Rivets where seen good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder efficient
 Plank (Bottom) and Counter " Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan in good order
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the deck
 Sails "
 Anchors, No. of 3 B. 1 S. 2 K
 Cables "
 Hawser and Warps "
 Standing and Running Rigging "
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

Clean'd and recoated the bottom
She is in good condition and entitled to remain as
Class'd 100. A. 1.
Samuel Presious

Committee's Minute 27th August 1875
 Character assigned 100 A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **No.** Survey held at London Date, first Survey Aug 14 Last Survey Aug 14 1875
 on the Iron Screw Steamer Terlings Master Jas Paton
 Tonnage 359, 572, 507 Built at Sunderland When built 1871 9th mth.
 By whom built Blumer Owners J. D. Hill
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 13874 Port of Iron Classed 85 A. 1.

Present Condition of the
 Decks good Treennails Rivets where seen good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder efficient
 Plank (Bottom) and Counter " Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan in good order
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained from the deck
 Sails "
 Anchors, No. of 3 B. 1 S. 2 K
 Cables "
 Hawser and Warps "
 Standing and Running Rigging "
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

Clean'd the bottom and recoated it
She is in good condition and entitled to remain as class'd 85 A. 1.
Samuel Presious

Committee's Minute 27th August 1875
 Character assigned 85 A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Atcham
Lerlyps



© 2019

Lloyd's Register
Foundation