

ANNUAL SURVEYS.

15089.

324.932

Recd. 25.8.75

No. in Reg. Book. **No.** 649 on the *S Simla* Survey held at *London* Date, first Survey _____ Last Survey *August 3^d 1875*
 Tonnage *1260* Built at *Liverpool* Master *Young*
 By whom built *Royden* Owners *J.A. Blunt*
 Port belonging to *Liverpool* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *13666* Port of *Trom* Classed *100A1* 11.76
 Present Condition of the Decks *Good* Freenails *Rivets* *Good*
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. *Painted* When put on *Now*
 Caulking of Bottom, Deck, & Waterways *Good*
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c. _____

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute *31st August 1875*

Character assigned *100A1*

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid _____ 18 _____

No. in Reg. Book. **No.** 192 on the *S Jane Porter* Survey held at *London* Date, first Survey _____ Last Survey *July 31st 1875*
 Tonnage *1100* Built at *Belfast* Master *Legg*
 By whom built *Harland* Owners *Corry & Sons*
 Port belonging to *Belfast* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Dry Dock*

Last Survey, No. *13479* Port of *Trom* Classed *A1* 10.76
 Present Condition of the Decks *Good* Freenails *Rivets* *Good*
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. *Painted* When put on *Now*
 Caulking of Bottom, Deck, & Waterways *Good*
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *Good*
 General Observations, Opinion as to Class, &c. _____

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute *31st August 1875*

Character assigned *100A1*

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid _____ 18 _____