

# ANNUAL SURVEYS.

Iron 15286

35078

No. 46 Survey held at London Date, first Survey 22<sup>nd</sup> Sep<sup>r</sup> Last Survey 22<sup>nd</sup> Oct<sup>r</sup> 1875  
 on the Ship "Hudson" Master Jewyn  
 Tonnage 833 Built at Stockton When built 1869-3 mo.  
 By whom built Pearse Owners Shaw Savill & Co.  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Princes by lock & Afloat

Last Survey, No. 13331 Port of London Classed Years assigned. # A. 1. Character in Register Book. # A. 1.

Present Condition of the  
 Decks Good Treennails Rivets Good S.C. Net-73. 9-74  
 Waterways — Breasthooks and Stems —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. Coat When put on 69  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom a keel sighted, cleaned and coated with Paint and Tallow, and the topsides with Paint.

She is now in good and efficient condition and eligible to remain as classed.

Committee's Minute 26<sup>th</sup> October 1875  
 Character assigned \* A 1 JW  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18—

No. 441 Survey held at London Date, first Survey 13<sup>th</sup> Oct<sup>r</sup> Last Survey 14<sup>th</sup> Oct<sup>r</sup> 1875  
 on the Ship "Duke of Argyll" Master Binnie  
 Tonnage 960 Built at Gumbarton When built 1865-10 mo  
 By whom built Rankin Owners Montgomerie & Co.  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Princes by lock

Last Survey, No. 12349 Port of London Classed Years assigned. # A. 1. Character in Register Book. # A. 1.

Present Condition of the  
 Decks Good Treennails Rivets Good S.C. Net-74. 8-74  
 Waterways — Breasthooks and Stems —  
 Comings — Transoms, Pointers, and Crutches —  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places —  
 Planksheers — Keelsons —  
 Sheerstrakes — Clamps and Shelves —  
 Topsides — Ceiling —  
 Wales — Rudder —  
 Plank (Bottom) and Counter — Copper or Y.M. Coat When put on 65  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom and keel sighted, cleaned and coated with Patent Composition and the topsides with Paint.

She is now in good and efficient condition and eligible to remain as classed.

Committee's Minute 26<sup>th</sup> October 1875  
 Character assigned \* A 1 JW  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18—