

15291
ANNUAL SURVEYS.

No. in Reg. Book. **No.** 2574 Survey held at London Date, first Survey Sept 8 Last Survey Sept 8 1875
on the S Thomas Stephens Master J Stephens
Tonnage 1507 Built at Liverpool When built 1869 7M
By whom built Potter Owners J Stephens
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13336 Port of London
Present Condition of the
Decks Good Freenails Good Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Painted When put on Now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom Scraped Painted & Crated
She is now in an efficient state of repair and entitled to remain as Classed

Committee's Minute 28th September 1875
Character assigned TRW
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **No.** 945 Survey held at London Date, first Survey Aug 23 Last Survey Sept 13 1875
on the S Star of Denmark Master Legg
Tonnage 998 Built at Belfast When built 1863 6M
By whom built Harland Owners Carry &
Port belonging to Belfast Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 13280 Port of London
Present Condition of the
Decks Good Freenails Good Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Painted When put on Now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom Scraped Painted & Crated
She is now in an efficient state of repair and entitled to remain as Classed

Committee's Minute 28th September 1875
Character assigned TRW
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____