

ANNUAL SURVEYS.

15578

Rev 3/1/76

No. in Reg. Book. 273 No. 13054 Survey held at Newcastle Date, first Survey 18th Nov. Last Survey 1st Dec^r 1875
 on the S.S. Cartago Nova Master R. Gillon
 Tonnage 1336 Built at Newcastle When built 1870-11 mo.
 By whom built Palmer Owners Hall Bros
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Palmer Dock

Last Survey, No. 14234 Port of Newcastle Iron Classed _____ Years assigned. _____ Character in Register Book. 90 A 1
3.75
 Present Condition of the Decks good Reeds good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel having touched the ground, was docked & one starboard plate on starboard side renewed, Bottom cleaned & painted. She is now in good condition & eligible in my opinion to remain as classed

Damage survey fee £2.2.0 Jan 1876

Committee's Minute 4th January 1876 Geo. I. Cooper
 Character assigned 90 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. 454 No. 13056 Survey held at S. Shields Date, first Survey 20th Dec^r Last Survey 24th Dec^r 1875
 on the S.S. Woodburn Master Thompson
 Tonnage 1153 Built at Newcastle When built 1874-5 mo.
 By whom built Palmer Owners Hutchinson & McEldy
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Edwards' Dock

Last Survey, No. 12944 Port of Newcastle Iron Classed _____ Years assigned. _____ Character in Register Book. 90 A 1
4.75
 Present Condition of the Decks good Reeds good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. — When put on —
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel having touched the ground was docked & the bottom scraped & chipped & repainted. She is now in good condition & eligible in my opinion to remain as classed

Damage survey fee £2.2.0 Jan 1876

Committee's Minute _____ 18 _____ Geo. I. Cooper
 Character assigned 90 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____