

Iron N^o 15747

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Rec'd 13.8.75)
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 25 June 1875
319 on the Cocks and Piping of S. S. Italia 447 Tons
Owners Gen. Ste. Ship Coy Port belonging to London Classified _____ Years assigned _____ Character in Register Book. A 1

Diameter of Cylinder 40" Engines made at Newcastle YEAR. When made 1869
Length of Stroke 30"
Pressure of Steam 12
Nominal Horse Power 46 By whom made Palmer

Particulars of Repairs and Examination

On examination the Cocks and piping in connection with the Machinery and Boilers of this vessel were found to be so arranged that water could not be run from the sea into the bilge by an act of carelessness or neglect

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to

(The Surveyors are requested not to write on or below the space for Committee's Minute).

The Amount of Fee ... £ : : received by me, _____
Certificate (if required) ... £ : : 187 _____
(Travelling Expenses, if any, £ _____)

Committee's Minute

18

Ames Bain
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register
Foundation

IRON464-0515