

* 15829

Report of Survey for Repairs of Engines and Boilers.

(Revised 13.8.73)

No. _____
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey June 12th 1875

852 on the Cocks and Piping of S. S. Medora 966 Tons

Owners Gen. Mm. Ship. Coy Port belonging to London Classed _____ Years assigned. _____ Character in Register Book. 80A1

Diameter of Cylinder 25" and 48" Engines made at Newcastle When made 1871
Length of Stroke 30"
Pressure of Steam _____
Nominal Horse Power 140 By whom made T. & W. Hawthorn

Particulars of Repairs and Examination

The Cocks and piping in connection with the Machinery and Boilers of this vessel have been examined and found so arranged that by an act of carelessness or neglect water cannot be run from the sea into the bilge

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }
(Travelling Expenses, if any, £ _____)

Amos Bacon
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ 18
End 18.12.75

