

1586
ANNUAL SURVEYS.

Rev. 3/3/76

Book No. 3592 Survey held at Bristol
 on the Screw Steamer "Aragon" Master Symonds
 Tonnage 1317 Built at Glasgow When built 1869, 10 months.
 By whom built Barclay Owners W. Whitewill & Co of Bristol
 Port belonging to Bristol Destined Voyage New York.
 Surveyed Afloat or in Dry Dock Bristol

Last Survey, No. 15849 Port of

Bristol Iron

Classed A.I.

S.S. No. 15849 Span decked
 Windlass and Capstan Steam Winches very good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Sails All in excellent Order
 Anchors No. of Correct in Weight
 Cables Two now ranged in Cock Pairs
 Hawsers and Warps Correct in length & size
 Standing & Running Rigging in good Order

The present Condition of the

Decks Very good
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Plankshears do
 Sheerstrakes do
 Topsides do
 Wales do
 Plank (Bottom) and Counter do

Fastenings Rivets & Nuts very good
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame do
 Keelsons do
 Clamps and Shelves do
 Ceiling do
 Rudder very good (hangings refitted)
 Copper when put on

General Observations and Opinion,

This steamer has been placed in dry dock, bottom and sides scraped clean, also all the frames and plating inside, and all well coated with two coats of paint, and engine and boilers thoroughly overhauled and cleaned. Also the timbers and structures cleaned.

Committee's Minute

7th March 1876Survey Fee £2. 0s. 0d
Certificate 5. 0s.

Henry Follett

(Certificate if required)

Book No. 3593 Survey held at Bristol Date 28 Feb 29th 1876
 No. 665 on the Screw Steamer "Edith Queen" Master W. H. Dart
 Tonnage 497 Built at Newcastle When built 1864, 9 months
 By whom built Marshall Owners Powell & Co
 Port belonging to Liverpool Destined Voyage Liverpool
 Surveyed Afloat or in Dry Dock Floating Harbour Bristol

Last Survey, No. 15883 Port of

Bristol Iron

Classed A.I.

S.S. No. 2. 55 2. 56

The present Condition of the

Decks Very good
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Plankshears do
 Sheerstrakes do
 Topsides do
 Wales do
 Plank (Bottom) and Counter do

Fastenings Rivets Very good
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame do
 Keelsons do
 Clamps and Shelves do
 Ceiling do
 Rudder do
 Copper when put on

Windlass and Capstan Steam Winches very good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Sails all in good Order, do
 Anchors No. of Correct in Weight
 Cables Length, size and
 Hawsers and Warps quantity & very good
 Standing & Running Rigging in good Order

General Observations and Opinion,

This vessel having grounded on the bank of the River Avon, and remained until the flood tide, has been examined in all her fastenings, outside to light water mark, and in every part inside, and all found perfectly good, and not strained, and has not made any water. I therefore consider her worthy her present class.

Committee's Minute 7th March 1876Survey Fee £2. 2s. 0d
Rec'd. Henry Follett
Mch 10/76

Character assigned A.I.

R.W.

Hoyt
Registered
Foundation