

ANNUAL SURVEYS.

Rec 20/3/76

No. in Reg. Book. **No. 13120** Survey held at Newcastle Date, first Survey and Last Survey 28 February 1876
 on the S.S.S. "Boadicea" Master Smith
 Tonnage 865 Built at Newcastle When built 1872 - 5 mo.
 By whom built Leslie Owners Adamson & Co
 Port belonging to North Shields Destined Voyage
 If Surveyed Afloat or in Dry Dock Leslie's Dock

Last Survey, No. 14081 Port of Newcastle Iron Classed Spur Clecked 3/5
 Present Condition of the
 Decks Good. Treenails Rivets Good.
 Waterways do. Breasthooks and Stenson do.
 Comings do. Transoms, Pointers, and Crutches do.
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do.
 Planksheers do. Keelsons do.
 Sheerstrakes do. Clamps and Shelves Stringers do.
 Topsides do. Ceiling do.
 Wales do. Rudder do.
 Plank (Bottom) and Counter do. Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good
 General Observations, Opinion as to Class, &c.

This vessel has been docked and the bottom cleaned and recoated, she appears to be in good condition and eligible in my opinion to remain as classed 90A1.

Committee's Minute 21 March 1876
 Character assigned 90A1 J.H. Cooke
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. **No. 13120** Survey held at Newcastle Date, first Survey and Last Survey 29 February 1876
 on the S.S.S. "Rowena" Master W. Stacey
 Tonnage 644 Built at Newcastle When built 1868 - 6 mo.
 By whom built Mitchell Owners Adamson & Short
 Port belonging to Newcastle Destined Voyage
 If Surveyed Afloat or in Dry Dock Wallsend Slipway

Last Survey, No. 13743 Port of Newcastle Iron Classed 4/4
 Present Condition of the
 Decks Good. Treenails Rivets Good.
 Waterways do. Breasthooks and Stenson do.
 Comings do. Transoms, Pointers, and Crutches do.
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do.
 Planksheers do. Keelsons do.
 Sheerstrakes do. Clamps and Shelves Stringers do.
 Topsides do. Ceiling do.
 Wales do. Rudder do.
 Plank (Bottom) and Counter do. Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated, she appears to be in good condition and eligible & in my opinion to remain as classed A1.

Committee's Minute 21 March 1876
 Character assigned A1 J.H. Cooke
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18