

# ANNUAL SURVEYS.

Report No. 4220

R.B. No. 995 Survey held at Glasgow Date 12<sup>th</sup> April 1876 Rec'd 24/4/76  
on the S. S. State of Virginia Master Moodie  
Tonnage 1594 Built at Glasgow When built 1873 - 3 mo.  
By whom built London & Glasgow Owners The State Steam Ship Co. Limited  
Port belonging to Glasgow Destined Voyage Clyde to New York  
If Surveyed Afloat or in Dry Dock In Goran Dry Dock and Afloat

Last Survey, No. 15090 Port of Iron Classed 100A1  
7.75

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson		<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches		<u>do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places		<u>do</u>	Sails	<u>Well Found</u>
Planksheers	<u>do</u>	Keelsons		<u>do</u>	Anchors, No. of	<u>3 B. 1. S. 2 K.</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>Securities</u>	<u>do</u>	Cables	<u>Complete</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>	Hawsers and Warps	<u>Well Found</u>
Wales	<u>do</u>	Rudder		<u>do</u>	Standing and Running Rigging	<u>In good order</u>
Plank (Bottom) and Counter	<u>do</u>	Copper	<u>Paint</u>	When put on <u>Now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Bottom cleaned, a few rivets renewed in Keel as well as Post, a few in frames, about 50 in Rudder, a few in Head Beam knees and stringer aft - Bottom re-coated

Committee's Minute 21<sup>st</sup> April 1876

Saml. Saphorn

Character assigned 100A1 TRM

Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
Certificate (if required).  
Foundation