

# ANNUAL SURVEYS.

*16680*  
**No.** 425 Survey held at Antwerp Date 7 & 8 July 1876  
 on the P. L. Lio Lijo, late "Haringstoker" Master A. Savary  
 Tonnage 649 Built at Newcastle When built 1865 - 9 m.  
 By whom built Ambridge Owners Companhia Litois  
 Port belonging to Operto Destined Voyage Antwerp - Havre  
 If Surveyed Afloat or in Dry Dock in dry dock

Last Survey, No. 10888 Port of Lyon Classed A. 1.

The present Condition of the

Decks <u>medium, good</u>	Treenails <u>fixes</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>&amp; water tanks</u>	Anchors, No. of <u>6</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>sufficient in size &amp; length</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>good</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>beat for</u> When put on <u>new</u>	

General Observations and Opinion,

*Placed in dry dock, scraped and painted bottom; repaired & rebushed rudder. Examined the Vessel all inside & outside and found her throughout in good condition but very unclean; the upper deck in some places considerable worn; but perfect watertight; I recommend that the Vessel should be continued as classed for another year; and then to be submitted to S. S. No. 3<sup>rd</sup> July*

Committee's Minute 14<sup>th</sup> July 1876

Character assigned B. 1

See rec. L. 2 " 5 "

Certificate (if required). yes

**No.** \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_

