

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** Survey held at London Date, first Survey Aug 26 Last Survey Sept 5 1876

201 on the SS Aegean Master _____

TONNAGE under Tonnage Deck 688
 Ditto of Spar Deck, or Awning Deck _____
 Ditto of Poop _____
 Ditto of Raised Qr. Dk. _____
 Ditto of Houses on Deck _____
 Ditto of Forecastle _____
 Gross Tonnage 1113
 Crew Space, as per Rule _____
 Register Tonnage, cut on Beam _____
 Engine Room _____
 Reg. Tons as St' mer, cut on Bm. 836

Built at Glasgow When built 1870 5

Owners C. Williamson Port belonging to Leith

Residence _____

By whom built London & Glasgow Co Destined Voyage _____

If Surveyed Afloat or in Dry Dock Afloat & by St

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.

Last Survey, No. 16374 Port Iron

Classed A1 11.75
 ss London 74

REPAIRS, OR EXAMINATION AS PER RULE

at the present time owing to damage
 Starboard side, Renewed one plate in the upper
 deck-sheer stake plate, and a plate below with
 taken off straightened and rivetted, gunwale
 angle repaired, gunwale iron moulding and the
 iron moulding below ditto taken off straightened and
 rivetted, one frame strengthened with an additional
 angle iron, 5 iron roughing stanchions one length of
 rail & two iron bulwark rails repaired,
 one length of deck next further gunwale patch pine

Bottom Scraped & coated

Present Condition of the	Good	Tree nails	Rivets	Good	Windlass and Capstan
Decks	Good	Breasthooks and Stenson	Good	Pumps	
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	
Comings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	Good &
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	Sufficient
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	where
Planksheers	"	Clamps and Shelves	"	Anchors No. of 3 Pro. & 8 Ref.	they
Sheerstrakes	"	Ceiling	"	Cables	could
Topsides	"	Rudder	"	Hawsers and Warps	be seen
Wales	"	Copper Coated When put on	new	Standing & Running Rigging	
Plank (Bottom) and Counter	"	Caulking of			
Engine Room Skylights	Good	Bottom, Deck, & Waterways	Good		
Coal Bunker, Openings, Lids, &c.	Good	Scuppers	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.				Hatches	Good

She is now in an efficient state of
 repair and entitled to remain as classed.

The Amount of Entry Fee ... £ : : received by me, }
 Special ... £ 2 : 2 : 16 Sep 1876 }
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 19 September 1876

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
 Lloyd's Register
 Foundation
 R0N467-0438