

1683

# Report of Survey for Repairs of Engines and Boilers.

No. 4285

No. in Reg. Book. Survey held at

Glasgow

Date, first Survey April 19<sup>th</sup> Last Survey Aug 10<sup>th</sup> 1876

1332 on the

S. S. Atholl

Tons 992.67  
1436.30

Owners

J. Warrack & Coy

Port belonging to

Leith

Classed

Years assigned.

Character in Register Book.

95-A.1

YEAR.

When made 1870-62

meter of Cylinder 33" & 60" one of each

Length of Stroke 39"

Engines made at

Glasgow

Pressure of Steam

65 lbs

nominal Horse Power

170

By whom made

J. Howden & Coy

## Particulars of Repairs and Examination

High pressure cylinders with Slide Valve. New Low pressure Cyl. bored out. Pistons turned up & fitted with through rods. Slide Valve gear altered & thoroughly overhauled. Piston block overhauled. Screw Shaft turned up. Stem bush rebushed. Sea cocks & all connections grounded & overhauled in Dry Dock. Propeller blades joined with plate iron where broken.

Main Boilers New.

Dowry Boiler repaired.

The above repairs have been satisfactorily completed by James Shaw & James Thomson, Glasgow.

The Amount of Fee ... £ 5: 5: received by me,


Certificate (if required) ... £ : : Aug. 1876

(Travelling Expenses, if any, £ 1. 11. 6)

Committee's Minute

18

James Morrison  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register  
Foundation

IRON467-0466