

REPORT of SURVEY for REPAIRS, &c.

16879

Rec 21/8/76

No. in Reg. Book. **No 7039** Survey held at **Port Glasgow** Date, first Survey **4th July** Last Survey **11th August 1876**
 on the **San Roque "Coppesfeld"** Master **J. Beith**
 Tonnage $\frac{454}{403}$ built at **Renfrew** When built **1868 - 4 mo**
 By whom built **Henderson** Owners **Scrutton Sons & Co**
 Port belonging to **London** Destined Voyage _____
 If Surveyed Afloat or in Dry Dock **Dry Dock & afloat**

Last Survey, No. **13436** Port **Glyde Iron S.S. No. 73** Classed **A.1.** Years assigned. **10-74** Character in Register Book. **A.1.**

REPAIRS, OR EXAMINATION AS PER RULE of Damage from being on shore
 Now done: Hold cleared except Coals Amidships for stiffening
 bottom and Keel coated with black Varnish and paint above.
 The following anchors and Chain cables now supplied to
 replaced those lost viz:-
 One Bow Anchor De Stock 16.3.2 Tested to 18.0.2.14 2nd August 1876
 Small " " " " 14.1.19 Tested to 15.19.0.7 31st July 1876
 30 fathoms Chain cable 1st Tested to 34 B.S. 51 7th Aug. 1876
 15 " " " " 1st Tested to 34 B.S. 51 31st July 1876
 Steam anchor 6" 1.12 including stock

Glasgow
Proving House
William Fraser
Superintendent

Cause of Repairs to be clearly stated.

Present Condition of the	Rivets	
Decks Good where seen	Greenails Good where seen	Windlass and Capstan Good
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained By observation
Planksheers	Keelsons	Sails Well found
Sheerstrakes	Clamps and Shelves	Anchors No. of 3 B. 18. 2 K.
Topsides	Ceiling	Cables Good & sufficient
Wales	Rudder	Hawsers and Warps
Plating	Copper <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	Standing & Running Rigging
Plank (Bottom) and Counter	Caulking of	
Engine Room Skylights	Bottom, Deck, & Waterways Good where seen	
Coal Bunker, Openings, Lids, &c.	Scuppers Good	Cargo and Main Hatchways Good
General Observations, Opinion as to Class, &c.		Hatches Good

I am of opinion this Vessel is eligible to remain as Classed

The Amount of Entry Fee ... £ 0: 0: 0 received by me, **H. J. B. 1800**
 Special Certificate (if required) ... £ 1: 1: 8 15 Aug 1876
 (Travelling Expenses, if any, £ ...)

Committee's Minute **22. August 1876**

Character assigned **A.1.**

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
 Foundation