

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 4490** Survey held at **Full** Date, first Survey **7th Sept** Last Survey **28th Sept 1876**
79 on the **Iron Ship Hannibal** Master **Brown**
 TONNAGE under Tonnage Deck **1122** Built at **Glasgow** When built **1862**
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage **1235** Owners **Thos. Main & Montgomery** Port belonging to **Liverpool**
 Crew Space, as per Rule
 Register Tonnage, cut on Beam **1186** Residence **Liverpool**
 Engine Room By whom built **Sonitts** Destined Voyage
 Reg. Tons as S^rmer, cut on Bm. If Surveyed Afloat or in Dry Dock **In (or rather in) dry dock & afloat in Albert St**

Length of Poop **ft.** Ditto, Forecastle **ft.** Ditto, Raised Quarter Deck **ft.** Years assigned. **2.75** Character in Register Book. **A 1**

Last Survey, No. **15219** Port **Iron**

Classed **SS. 6/102-71**

REPAIRS, OR EXAMINATION AS PER RULE **Survey No. 3**

The close ceiling in the Holds removed and the plating outside and inside from cement upwards scraped or chipped clean and painted. Cement removed where required and thickness ascertained by drilling by 12/16 7/16 & 9/16. Windlass turning linings stripped. Chain cables on Deck. Now done. Cement repaired where required. Ceiling removed where required & remainder retained to top of bilge from thence to Hold Beams Spar called.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treesails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of **3 B 1 S 1 2 Redg.**

Cables **370 lbs.**

Hawsers and Warps

Standing & Running Rigging

The Amount of Entry Fee ... £ 5 : - : - received by me, **Mr. Davidson**

Special ... £ 6 : 6 : - 28th Sept 1876

Certificate (if required) ... £ - : 5 -

(Travelling Expenses, if any, £)

Committee's Minute **Mr. Keydell 21/3 October 1876**

Character assigned **SS. No 3-76**

Surveyor to Lloyd's Register of British and Foreign Shipping.

Mr. Keydell

Lloyd's Register Foundation

180463-0070