

ANNUAL SURVEYS.

No. 19 Survey held at London Date, first Survey 12.10.76 Last Survey Oct 18 1876
 Reg. Book. on the S Kapunda Master Trinder Anderson & Co
 Tonnage 1084 Built at Dumbarton When built 1875
 By whom built M. Millan Owners Trinder Anderson & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 14747 Port of Iron Classed 100 A1 6.75
 Present Condition of the
 Decks Good Treennails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Panels When put on Mon
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute 20th October 1876

Character assigned 100 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 203 Survey held at London Date, first Survey Sept 28 1876 Last Survey Sept 28 1876
 Reg. Book. on the BK Santiago Master Moffat
 Tonnage 460 Built at Methil When built 1856
 By whom built ✓ Owners Balfour Williamson & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock Ballast & Lumber in

Last Survey, No. 14658 Port of Iron Classed 88 A1 5.75
 Present Condition of the
 Decks Good Treennails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Panels When put on Mon
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed

Senhouse Martindale

Committee's Minute 20th October 1876

Character assigned 88 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18