

*17453

Report of Survey for Repairs of Engines and Boilers.

No. *10348*

No. in Reg. Book. *633* Survey held at *Glasgow*

Date, first Survey *Oct 25th* Last Survey *Nov 28th 1876*

633 on the *S. S. "Jura"*

Tons *220*
362

Owners *J. Bell* Port belonging to *Glasgow*

Classed *A.1*
12 1/2

Diameter of Cylinder *20" x 36"* Engines made at *Glasgow* When made *1873*
Length of Stroke *24"*
Pressure of Steam *60 lbs* By whom made *David Rowan*
Nominal Horse Power *50*

Particulars of Repairs and Examination of Engines. *Cylinders opened up & Pistons examined. H. Slide Valve & Expansion Valve, new; Link Motion renewed. Condenser retubed. Propeller Shaft new. Stem Bush, new. Sea cocks ground & overhauled in Dry Dock. Pumps, overhauled. Safety Valves on Main & Turkey Boilers, scraped up. - Main Boiler, retubed.*

The above repairs have been satisfactorily completed by David Rowan.

(Condition of survey ent Repairs and Examinations, to be clearly stated.)

(Condition of)

surveys are requested not to write on or below the space for Committee's Minute).

The Amount of Fee *£ 1 : 1 : -* received by me, *4th*
Certificate (if required) *£ " : " : -* Dec 1876
(Travelling Expenses, if any, £ *1 : 1 : 0*)

James Hollison
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute *18*



IRON 469 - 0289