

REPORT of SURVEY for REPAIRS, &c.

No. 4028 Survey held at Cardiff Date, first Survey 24 Jan 1877 Last Survey 24 Jan 1877
 in the S.S. "Minerva" Master Blackclaw
 AGE under Tonnage Deck 1538 Built at W. Martlepool When built 1874
 of Spar Deck, or Avoing Deck Owners W. & W. Wise & Son Port belonging to W. Martlepool
 of Poop Residence W. Martlepool
 of Raised Qr. Dk. By whom built Gray Destined Voyage Bombay
 of Houses on Deck If Surveyed Afloat or in Dry Dock East Bute Dry Dock
 of Forecastle Tonnage 1689
 as Tonnage ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck
 no Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 eg. Tons as St'mer, cut on Bm. 1025
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck
 Last Survey, No. 14462 Port Iron
 Classified 90.1.1
 5.75

REPAIRS, OR EXAMINATION AS PER RULE

Now Supplied
 1 Bower Anchor (Porters) W. & W. Wise & Son 24.2.16 proved to 26.16.3.14
 Certificate dated Glasgow 6th July 1876
William Fraser
 30 1/2 fms 1 1/4 in Stud Link Chain proved to 55.125 3 links of ea 15
 fms to B.S. Certificate dated Glasgow 9 Jan 1877
William Fraser

Present Condition of the

| | | |
|----------------------------------|--------------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stenson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelves | Anchors No. of |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsers and Warps |
| Plank (Bottom) and Counter | Copper When put on | Standing & Running Rigging |
| Engine Room Skylights | Caulking of | |
| Coal Bunker, Openings, Lids, &c. | Bottom, Deck, & Waterways | |
| Scuppers | | |
| Cargo and Main Hatchways | | |
| Hatches | | |

General Observations, Opinion as to Class, &c.

The above Anchor and Chain, as recommended in Loudon Report
 No. 16 dated 16 Jan 1877 and here with returned, have now
 been supplied here, and test certificates produced as reported.

The Amount of Entry Fee ... £ : : received by me, 30/1 1877
 Special ... £ : :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute 2nd February 1877
 Character assigned 90.1.1
W. & W. Wise & Son

Henry J. Gynell
 Surveyor to Lloyd's Register of British and Foreign Shipping.

"Mierva"



© 2019

Lloyd's Register
Foundation