

17981 Sm
Report of Survey for Repairs of Engines and Boilers.

No. 25474

No. in Reg. Book. Survey held at

Birkenhead

Date, first Survey

2^d Feb 1877

Last Survey

16 Feb 1877

1877

296 on the

S.S. "Richmond"

Master

Harvey

Tons 676-1080-1079

Owners

J. Dixon Esqr

Port belonging to

London

Classed

90 A1

Character in Register Book.

Lon No 1875

Diameter of Cylinder

1 of 38" - 1 of 53

Length of Stroke

33

Engines made at

Hartlepool

When made

YEAR.

1871

Pressure of Steam

60 stated

By whom made

Richardson

Registered Horse Power

150

Particulars of Repairs and Examination

The Boilers scaled cleaned and retubed throughout. Engines overhauled and part examined. Propeller shaft drawn in, stern bush relined with lignumvitae.

A sufficient opportunity was not given me to examine engines and boilers for the machinery certificate. But so far as could be seen are in good order and in my opinion entitle the vessel to retain the figure 1.

The Amount of Fee ... £ : : received by me,

Certificate (if required) ... £ : : 187

(Travelling Expenses, if any, £

Committee's Minute

Liverpool March 9th 1877

90 A1.

J. H. L.

J. G. Wingham

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation