

ANNUAL SURVEYS.

36004

No. in Reg. Book. on the 7145 No. 122 Survey held at London Date, first Survey 4th Mar Last Survey 9th March 1877
 Tonnage 454 Built at Penryn When built 1868 4 mo.
 By whom built Henderson Owners Scrutton
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fletcher's dock

Recd 26.3.77

Last Survey, No. 16879 Port of London

Years assigned. _____ Character in Register Book. _____
 Classed SA 1 8 76
S.S. M.I. 73.

Present Condition of the Decks _____	Keelsons _____	Windlass and Capstan _____
Waterways _____	Clamps and Shelves _____	Pumps _____
Comings _____	Ceiling _____	Boats _____
Upper Deck Beams & Fastenings _____	Rudder _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Copper or Y.M. _____ When put on _____	Condition, how ascertained _____
Planksheers _____	Caulking of Bottom, Deck, & Waterways _____	Sails _____
Sheerstrakes _____	Bottom, Deck, & Waterways _____	Anchor, No. of _____
Topsides _____	Coal Bunker, Openings, Lids, &c. _____	Cables _____
Wales _____	Scuppers _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Cargo and Main Hatchways _____	Standing and Running Rigging _____
Engine Room Skylights _____	Hatches _____	

General Observations, Opinion as to Class, &c.
Bottom cleaned and recoated.
It is proposed to have 2nd survey held on the vessel's return, and which has been sanctioned by the Committee in a letter to Comr of 13th Mar 1877.

Committee's Minute 29th March 1877
 Character assigned SA 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

IRON 470-0523