

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Recd 20.4.77.)
 No. in Reg. Book. Survey held at London Date, first Survey in Last Survey 16th April 1844
 on the Boiler of S.S. Bee Master _____
 Tons 299 Owners Adam & Co Port belonging to Aberdeen Classified 90A1

Diameter of Cylinder 20" & 30" Engines made at Glasgow When made 1843
 Length of Stroke 20" By whom made Smith, Bros & Co
 Pressure of Steam 60 lb
 Rated Horse Power 111

Particulars of Repairs and Examination

On Examining boiler found defective plate in back of st^o combustion chamber. The owners have intimated that it is their intention to have this plate removed at the earliest opportunity and their representative here has promised to give notice when the vessel next arrives in this port so that the boiler may again be inspected. In order to stiffen defective parts additional stays have at this time been fitted in back of combustion chamber.

It is respectfully submitted that the vessel is eligible to remain as classed in the Register Book.

The Amount of Fee ... £ : : received by me, }
 Certificate (if required) ... £ : : 187 }

(Travelling Expenses, if any, £ _____)

Committee's Minute _____ 18

James Bain

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation