

No 24721
(in Ship)
18285

Report of Survey for Repairs of Engines and Boilers.

No. _____
No. in Reg. Book. Survey held at Liverpool Date, first Survey 15th July Last Survey 19th July 1875
on the Iron S.S. Fire Queen Tons 757-1112-697
Owners A. J. Harrison Port belonging to Liverpool Classified _____ Years assigned _____ Character in Register Book. A1.

Diameter of Cylinder S 41.25" diam L.P. 50" diam YEAR. _____
Length of Stroke 36 Ins. Engines made at Liverpool When made 1872
Pressure of Steam 75 lbs.
Nominal Horse Power 180 By whom made Jones & Son

Particulars of Repairs and Examination For Spl. S. No 2,

The vessel placed in graving dock. Propeller, Propeller shaft, bushes and liners found good as far as seen. shaft has not be drawn at this time. Sea chests and cocks found good. Boilers examined throughout and found good. These cleaned and overhauled run.
No opportunity having been given for an inspection of the Engines and connections at this time in consequence of the vessel having to sail. Survey to be completed on her return from present voyage.
See Owners letter appended

The Amount of Fee ... £/ :/ : received by me, 10/8 1875
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £ _____)

J. G. Kinghorn
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ 18