

REPORT of SURVEY for REPAIRS, &c.

Row: 18482

Reg. 28/5/77

No. in Reg. Book. **No. 11642** Survey held at Sunderland Date, first Survey 17th May Last Survey 18th May 1877
on the Iron Screw Steamer "Elsie" Master C. Needham.

Official Number 72 Ep	TONNAGE under Tonnage Deck	936.	Built at	Sunderland	When built	1877	YEAR.	MONTH.
	Ditto of Spar Deck, or Awning Deck		Owners	Gordon and Stamp.	Port belonging to	Sunderland.		
	Ditto of Poop		Residence	John St. Sunderland.				
	Ditto of Raised Qr. Dk.		By whom built	L. L. Thompson and Sons	Destined Voyage	Cronstadt.		
	Ditto of Houses on Deck		If Surveyed Afloat or in Dry Dock	afloat.				
	Ditto of Forecastle	1183						
	Gross Tonnage							
	Crew Space, as per Rule							
	Register Tonnage, cut on Beam							
	Engine Room							
Reg. Tons as St' mer, cut on Bm.	760.							
Length of Poop	ft.	Ditto, Forecastle	ft.	Ditto, Raised Quarter Deck	ft.	Years assigned.	Character in Register Book.	
Last Survey, No. 18369	4652	Port	Sunderland	Iron	Classed	-	90. A. I.	5/77.

REPAIRS, OR EXAMINATION AS PER RULE caused by alteration:-

Work done:- In order to fulfil the conditions of the contract between the Builders and owners as to her right to be carried and to make her self-trim more perfectly. Removed the whole of the dross ceiling in both cargo holds and fitted 2 1/2 in Baltic-plank in lieu thereof. Made some slight alterations and additions to the fore-hatches. The structural strength of the vessel has not been impaired thereby. The whole having been efficiently carried out. The water-tanks have been removed from the fore-hold and placed in the after-hold.

Present Condition of the

Decks	} Good.	Twists.	} Good.	Windlass and Capstan	} Good.
Waterways		Treenails		Pumps 3 1/2	
Comings	} Good.	Breasthooks and Stemson.	} Good.	Boats 3 1/2 - the 1st	} Good. also.
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Boats 3 1/2 - the 2nd	
Lower Deck Beams & Fastenings	} Good.	Timbers of the Frame at the openings	} Good.	Masts, Yards, &c.	} Good. also.
Plank-keels		Ditto Ditto at other places		Condition, how ascertained	
" Sheerstrakes	} Good.	Keelsons	} Good.	Sails Complete	} Good.
" Topsides		Clamps and Shelves		Anchors No. of 15. 206.	
" Wales	} Good.	Ceiling	} Good.	Cables part seen	} Good.
" Plank (Bottom) and Counter		Rudder		Hawsers and Warps	
		Copper		Standing & Running Rigging	
		Caulking of			
		Bottom, Deck, & Waterways			
Engine Room Skylights	Efficient	Coal Bunker, Openings, Lids, &c.	Secure	Scuppers	Good
General Observations, Opinion as to Class, &c.				Cargo and Main Hatchways	Good
				Hatches	Good.

She is in good and efficient condition, and fit, in my opinion, to remain classed 90. A. I.

The Amount of Entry Fee ... £ ... received by me, }
Special ... £ ... 187 }
Certificate (if required) ... £ ...
(Travelling Expenses, if any, £ ...)

Committee's Minute 20th May, 1877.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 472-0083