

1860 ANNUAL SURVEYS.

Rec 14/6/77

No. in Reg. Book. 333 No. 13602 Survey held at South Shields Date, first Survey and Last Survey 27th May 1877
 on the Iron S.S. "William Hunter" Master W. Porteus
 Tonnage 493 Built at Newcastle When built 1865 - 2 mo.
 By whom built Palmer Owners J. Johnsson
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock Afloat - Dry Dock

Last Survey, No. 15856 Port of Lion Classed GOA1 Years assigned. 2 7/6 Character in Register Book.
 Present Condition of the
 Decks Good Treennails Rivets Good.
 Waterways do. Breasthooks and Stemson do. S.S. Sld. No. 2 - 74
 Comings do. Transoms, Pointers, and Crutches do. Windlass and Capstan Good.
 Upper Deck Beams & Fastenings do. ~~Timbers of the~~ Frame at the Openings do. Pumps do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do. Boats Three do.
 Planksheers do. Keelsons do. Masts, Yards, &c. do.
 Sheerstrakes do. Clamps and Shelves Stringers do. Condition, how ascertained From the deck & by inquiry
 Topsides do. Ceiling do. Sails Sufficient & Good.
 Wales do. Rudder do. Anchors, No. of do.
~~Ring~~ Plank (Bottom) and Counter do. Copper or Y.M. When put on do. Cables do.
 Engine Room Skylights Good. Coal Bunker, Openings, Lids, &c. Good Scuppers Good. Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

This vessel is in good condition and eligible in my opinion to remain as classed.

Special L. 1.1.0

Committee's Minute 15th June, 1877.

Character assigned

GOA1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. in Reg. Book. 732 No. 13602 Survey held at South Shields Date, first Survey and Last Survey 6th June 1877
 on the Iron S.S. "Amy Dora" Master J. Stephens
 Tonnage 1107 1/2 Built at Newcastle When built 1875 - 6 mo
 By whom built Cole Owners J. Robinson
 Port belonging to North Shields Destined Voyage
 If Surveyed Afloat or in Dry Dock Edwards Dock

Last Survey, No. 16364 Port of Newcastle Lion Classed GOA1 Years assigned. 5 7/6 Character in Register Book.
 Present Condition of the
 Decks Good Treennails Rivets Good.
 Waterways do. Breasthooks and Stemson do. Windlass and Capstan Good.
 Comings do. Transoms, Pointers, and Crutches do. Pumps do.
 Upper Deck Beams & Fastenings do. ~~Timbers of the~~ Frame at the Openings do. Boats Four do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do. Masts, Yards, &c. do.
 Planksheers do. Keelsons do. Condition, how ascertained From the deck & by inquiry
 Sheerstrakes do. Clamps and Shelves Stringers do. Sails Sufficient & Good.
 Topsides do. Ceiling do. Anchors, No. of do.
 Wales do. Rudder do. Cables do.
~~Ring~~ Plank (Bottom) and Counter do. Copper or Y.M. When put on do. Hawsers and Warps do.
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

The bottom has now been cleaned and recoated. She is in good condition, and eligible in my opinion to remain as classed.

Committee's Minute 15th June, 1877.

Character assigned

GOA1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18