

# ANNUAL SURVEYS.

No. in Reg. Book. on the *No. 12* Survey held at *London* Date, first Survey *13 June* Last Survey *15 June* 18*77*  
*12* Tonnage *638* Built at *Newcastle* When built *1865* 6 mo.  
 By whom built *Palmer* Owners *London & W. Ship Co.*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Lincolin dock*

Last Survey, No. *\*1632* Port of *Iron* Classed *1* 4 76  
 Present Condition of the Decks *Good*  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Engine Room Skylights  
 Coal Bunker, Openings, Lids, &c.  
 General Observations, Opinion as to Class, &c.  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M.  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawseers and Warps  
 Standing and Running Rigging  
 Hatches

*Bottom cleaned and recoated. This vessel appears eligible to remain as classed.*

Committee's Minute

10th July, 1877.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. in Reg. Book. on the *No. 79* Survey held at *London* Date, first Survey *20 June* Last Survey *20 June* 18*77*  
*79* Tonnage *1706* Built at *Glasgow* When built *1874* 3 mo.  
 By whom built *Murray* Owners *Royal Exchange & Compt*  
 Port belonging to *London* Destined Voyage  
 If Surveyed Afloat or in Dry Dock *Regent dry dock*

Last Survey, No. *14562* Port of *Iron* Classed *100* 21 5 75  
 Present Condition of the Decks *Good*  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Engine Room Skylights  
 Coal Bunkers, Openings, Lids, &c.  
 General Observations, Opinion as to Class, &c.  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M.  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawseers and Warps  
 Standing and Running Rigging  
 Hatches

*Bottom cleaned and recoated. This ship appears in good condition and eligible to remain as classed.*

Committee's Minute

10th July, 1877.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



Taberna

Eastern Monarch

---



© 2019

Lloyd's Register  
Foundation