

ANNUAL SURVEYS.

Recd 27.6.77.

No. in Reg. Book. on the **No.** 666 Survey held at London Date, first Survey 18/6/77 Last Survey 18 June 1877
 Tonnage 792 Built at Newcastle When built 1846 4 mo
 By whom built Schlesinger Owners J. Edwards & Co
 Port belonging to Cardiff Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 16446 Port of Liverpool Classed 90 1 5.76
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways Do Breasthooks and Stems _____
 Comings Do Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings Do Timbers of the Frame at the Openings where
 Lower Deck Beams & Fastenings Do Ditto ditto at other places seen
 Planksheers Do Keelsons _____
 Sheerstrakes Do Clamps and Shelves _____
 Topsides Do Ceiling Good
 Wales Do Rudder Good
 Plating (Bottom) and Counter Do Copper or V.M. Good When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Do Cargo and Main Hatchways Good Hatches Do
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 3rd July, 1877.

Character assigned 90A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. in Reg. Book. on the **No.** 906 Survey held at London Date, first Survey 21/6/77 Last Survey 21 June 1877
 Tonnage 796 Built at Sunderland When built 1844 12 mo
 By whom built Hampson Owners A. Smith & Co
 Port belonging to Sunderland Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 18302 Port of Liverpool Classed 90 1 4.77
 Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways Do Breasthooks and Stems _____
 Comings Do Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings Do Timbers of the Frame at the Openings where
 Lower Deck Beams & Fastenings Do Ditto ditto at other places seen
 Planksheers Do Keelsons _____
 Sheerstrakes Do Clamps and Shelves _____
 Topsides Do Ceiling Good
 Wales Do Rudder Good
 Plating (Bottom) and Counter Do Copper or V.M. Good When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Do Cargo and Main Hatchways Good Hatches Do
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 3rd July, 1877.

Character assigned 90A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18