

18992

Report of Survey for Repairs of Engines and Boilers.

No. _____

No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey July 18th 1877

1139 on the Screw Steamer Minerva Master _____

ns 427 Owners London Steamship Co Port belonging to London Classified _____ Years assigned. _____ Character in Register Book. 95 A 1

_____ Diameter of Cylinder 25 1/4 8 Engines Compound made at Newcastle When made 1870

_____ Length of Stroke 30 By whom made Palmer & Co

_____ Pressure of Steam 75 lbs. Registered Horse Power 140


Particulars of Repairs and Examination. The Engines of this vessel have been thoroughly overhauled, Crankshaft & Thrust journal examined and found good. Air & Circulating pumps & 2 Circulating pump barrel chipped fair. All sea connections examined and Boiler sea cocks removed to turn of helge in accordance with the Rules.

New main & Donkey boilers fitted. Engines tried under steam and found to work well, Safety valves set to blow off at 75 lbs per square inch. The whole of the machinery and boilers of this vessel are in good order and safe working condition.

The Amount of Fee ... £ 7 : 0 : 0 received by me, _____
 Certificate (if required) ... £ : : 16 Aug 1877
 (Travelling Expenses, if any, £ _____)

Committee's Minute _____ 14th August 1877

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation