

19083 REPORT of SURVEY for REPAIRS, &c.

in Book. No. 12665 Survey held at South Shields Date, first Survey 25th June Last Survey 9th July 1877

on the Iron S.S. "Vindomora"

Master W. West

Tonnage under Tonnage Deck 239

Ditto of Spar Deck, or Awaiting Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 1080

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm. 692

Built at Sunderland

When built 1873

Owners Bell & Symonds Port belonging to London

Residence Lombard Street, Newcastle on Tyne.

By whom built Thompson

Destined Voyage

If Surveyed Afloat or in Dry Dock Afloat at South Shields Buoy

Length of Poop 125 ft. Ditto, Forecastle 29 ft. Ditto, Raised Quarter Deck ft.

Classed

90A1

Last Survey, No. 17079 Port Newcastle

REPAIRS, OR EXAMINATION AS PER RULE

Now done on account of damage sustained by an explosion of gas while on her late voyage from Cardiff to Dieppe. A few of the bolts in the poop deck renewed. The after part of the deck recaulked. Wood bulkhead refitted parts renewed. Cabin skylight repaired.

Present Condition of the

Decks	Good.	Greenails Rivets	Good.	Windlass and Capstan	Good.
Waterways	do.	Breasthooks and Stemson	do.	Pumps	do.
Comings	do.	Transoms, Pointers, and Crutches	do.	Boats	do.
Upper Deck Beams & Fastenings	do.	Timbers of the Frame at the openings	do.	Masts, Yards, &c.	do.
Lower Deck Beams & Fastenings	do.	Ditto Ditto at other places	do.	Condition, how ascertained	From the deck & inquiry
Planksheers	do.	Keelsons	do.	Sails	Sufficient & Good.
Sheerstrakes	do.	Clamps and Shelves Stringers	do.	Anchor No. of	do.
Topsides	do.	Ceiling	do.	Cables	do.
Wales	do.	Rudder	do.	Hawsers and Warps	do.
Plank (Bottom) and Counter	do.	Copper When put on	do.	Standing & Running Rigging	do.
Engine Room Skylights	Good	Caulking of			
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good where tried		
Scuppers	Good	Cargo and Main Hatchways	Secure	Hatches	Good.

General Observations, Opinion as to Class, &c.

This vessel is now in good condition and eligible in my opinion to remain as classed

The Amount of Entry Fee ... received by me, T. Young
Special ...
Certificate (if required) ...
(Travelling Expenses, if any, £)

S. H. Cooke.
Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 14th August, 1877.

Character assigned 90 B Lloyd's M 6 7.77 for 12 mos