

REPORT of SURVEY for REPAIRS, &c.

19343 Iron

No. in Reg. Book. 4470 Iron

Survey held at *Cardiff* Date, first Survey *2nd Nov* Last Survey *5th Nov* 1878

on the *Baque "Star of the East."* Master *Pomroy*

TONNAGE under Tonnage Deck *675*

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage *757*

Crew Space, as per Rule

Register Tonnage, cut on Beam *734*

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at *Glasgow* When built *1876* 9

Owners *E. Smith* Port belonging to *Plymouth*

Residence *Plymouth*

By whom built *Cornell* Destined Voyage *Singapore*

If Surveyed Afloat or in Dry Dock *Roath Dry Dock*

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. *100* Character in Register Book. *100*

Last Survey, No. *19343* Port *Iron* Classed *100* 9.78

REPAIRS, OR EXAMINATION AS PER RULE

Placed on blocks in Dry Dock. The lower braces taken off the Post, and renewed. Rudder lifted and bushed; Keel well cleaned and coated with Paint Externally.

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Good *Paint where seen Good*

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves *Stringers &c*

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

The Vessel appears in good and efficient condition eligible to remain as classed 100.

The Amount of Entry Fee ... £ : : received by me, }

Special ... £ / : / : 18

Certificate (if required) ... £ : : :

(Travelling Expenses, if any, £)

Committee's Minute

28th January, 1879.

Character assigned

100

TRW

Henry J. Syrell

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 474-0067

Cause of Repairs to be clearly stated.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Star of the East



© 2019

Lloyd's Register
Foundation