

ANNUAL SURVEYS.

No. in Reg. Book. 269 No. 13749 Survey held at South Shields Date, first Survey and Last Survey 30th October 1877.
 on the Iron S.S. "Vindomora" Master W. West-
 Tonnage 622 Built at Sunderland When built 1873 - 7th
 By whom built Thompson Owners Bell & Symonds
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Edwards Dock

Last Survey, No. 19083 Port of Hewcastle Iron Classed 90A1
 Present Condition of the
 Decks Good. Treenails Rivets Good.
 Waterways do. Breasthooks and Stemson do.
 Comings do. Transoms, Pointers, and Crutches do.
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do.
 Planksheers do. Keelsons do.
 Sheerstrakes do. Clamps and Shells Stringers do.
 Topsides do. Ceiling do.
 Wales do. Rudder do.
 Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good where tried
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

The bottom has now been scraped and recoated, she is in good condition and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 18 77. J. H. Cooke.
 Character assigned 90A1 J. H. Cooke. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18

No. in Reg. Book. 710 No. 13749 Survey held at South Shields Date, first Survey 31st October and Last Survey 2nd November 1877.
 on the Iron S.S. "Chipschase" Master J. Reed.
 Tonnage 438 Built at Hewcastle When built 1864 - 3rd
 By whom built Richardson Owners J. W. Hughes & Co
 Port belonging to Hewcastle Destined Voyage London
 If Surveyed Afloat or in Dry Dock J. Young's Dock.

Last Survey, No. 16225 Port of Hewcastle Iron Classed B1
 Present Condition of the
 Decks Good. Treenails Rivets Good.
 Waterways do. Breasthooks and Stemson do.
 Comings do. Transoms, Pointers, and Crutches do.
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do.
 Planksheers do. Keelsons do.
 Sheerstrakes do. Clamps and Shells Stringers do.
 Topsides do. Ceiling do.
 Wales do. Rudder do.
 Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good where tried
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

The bottom has now been cleaned and recoated. She is in good condition, and eligible in my opinion to remain as classed.

Committee's Minute 9th November, 1877. J. H. Cooke.
 Character assigned B1 J. H. Cooke. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) PAID 18

IRON474-0544