

Report of Survey for Repairs of Engines and Boilers.

No. 49

No. in Reg. Book. Survey held at

South Shields

Date, first Survey

3rd and

Last Survey

25th Nov

1877

269 on the

S. S. "Indomoro"

Master H. West

Tons

692
839

Owners

Bell & Lymonds

Port belonging to

London

Classed

Years assigned.

Character in Register Book.

90 A1

7.77

YEAR.

Diameter of Cylinder

24 1/2

Length of Stroke

33"

Engines made at

Sunderland

When made

1873

Pressure of Steam

67 lbs

Registered Horse Power

99

By whom made

J. Dickinson

Particulars of Repairs and Examination

The machinery of this vessel damaged on my to this vessel getting aground on 23rd Oct - 77 as recorded in damage report has been efficiently repaired and otherwise made good. With new screw propeller fitted with stern tube both rebuilt. New crank shaft fitted and parts of engines examined considered necessary on account of this accident, no further damage was observed.

The machinery of this vessel is now in good order & safe working condition & in my opinion eligible to retain her Class in the Register Book.

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

Damage survey

The Amount of Fee ... £ 4 : 4 : received by me,

Certificate (if required) ... £ - : - : - 12th Dec 1877

(Travelling Expenses) ... £ - : - : -

Committee's Minute

18

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

George W. Marnell

North Shields
Machinery damaged
Submitted for repair
to remain as classed