

ANNUAL SURVEYS.

No. 19719 Survey held at London Date, first Survey 29/10/77 Last Survey 31 Oct 77 1877
 No. in on the S. James Michant Master Mitchell
 Reg. Book. 109 Tonnage 776 Built at Leith When built 1864 yrs
 By whom built Morton Owners M. Thompson & Co
 Port belonging to Leith Destined Voyage
 If Surveyed Afloat or in Dry Dock Repairs Dry Dock (with ballast in hold)

Last Survey, No. 17134 Port of Iron Classified S.S. Dub. No 3. 76 19.76
 Present Condition of the Decks Good Transoms Ribs Good
 Waterways Dr Breasthooks and Stemson Good
 Comings Dr Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Dr Timbers of the Frame at the Openings where
 Lower Deck Beams & Fastenings Dr Ditto ditto at other places where
 Planksheers Dr Keelsons where
 Sheerstrakes Dr Clamps and Shelves Good
 Topsides Dr Ceiling Good
 Wales Dr Rudder Good
 Plating (Bottom) and Counter Dr Copper or Y.M. Paint When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Dr Cargo and Main Hatchways Good Hatches Dr
 General Observations, Opinion as to Class, &c.

She now appears to be in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 4th December, 1877.

Character assigned A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 14854 Survey held at London Date, first Survey 14/11/77 Last Survey 28 Nov 77 1877
 No. in on the S. Vanguard Master Garnett
 Reg. Book. 41 Tonnage 688 Built at P. Glasgow When built 1852
 By whom built Nicholson Owners Nicholson
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock (with ballast in hold)

Last Survey, No. 14854 Port of Iron Classified S.S. Dub. No 3. 74 6.75
 Present Condition of the Decks Good Transoms Ribs Good
 Waterways Dr Breasthooks and Stemson Good
 Comings Dr Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Dr Timbers of the Frame at the Openings where
 Lower Deck Beams & Fastenings Dr Ditto ditto at other places where
 Planksheers Dr Keelsons where
 Sheerstrakes Dr Clamps and Shelves Good
 Topsides Dr Ceiling Good
 Wales Dr Rudder Good
 Plating (Bottom) and Counter Dr Copper or Y.M. Paint When put on how
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Dr Cargo and Main Hatchways Dr Hatches Dr
 General Observations, Opinion as to Class, &c.

She now appears to be in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 4th December, 1877.

Character assigned A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18