

\* 19782

# Report of Survey for Repairs of Engines and Boilers.

No. 42

No. in Reg. Book. Survey held at

Date, first Survey 13<sup>th</sup> of June Last Survey 11<sup>th</sup> of December 1877.

89 on the Iron Screw Steamer Baron Hambro Master Laverick

Tons 579  
367

Owners W. Tulley & Co

Port belonging to

Null

Classed

Years assigned.

Character in Register Book.

90 A1  
6.77

Diameter of Cylinder 20 1/2 x 40

Length of Stroke 26

Pressure of Steam 75 p. sq. inch

Registered Horse Power 60

Engines made at

Null

When made

1869

By whom made

Charles & W. Earle

## Particulars of Repairs and Examination

All working parts of Engines examined and adjusted. High pressure cylinder rebored. New High pressure valve rod. piston rods turned. Cylinder faces & Valves planed. Seacocks fitted according to the Societies rules.

New boiler made and fitted in accordance with the rules of the Society.

Engines tried in port on the 8<sup>th</sup> of Dec. in my presence.

Is in my opinion eligible for the Notification Layds M. C. in the Registerbook.

The Amount of Fee ... £ 4 : 4 : - received by me,

Certificate (if required) ... £ - : - : Dec. 19<sup>th</sup> 1877

(Travelling Expenses, if any, £ -)

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

21st December, 1877.

H. Keywell



© 2019

Lloyd's Register Foundation

120N475-0120