

* 19906

26871

Report of Survey for Repairs of Engines and Boilers.

No. _____
 No. in Reg. Book. 234 on the 1258 2019 Survey held at Southampton Date, first Survey _____ Last Survey 26th Nov. 1877
African Master G. Larmer

Tons 1258 2019 Owners Union SS Co Port belonging to Southampton Classified 100A 1 SS No: 1-77 12.77
 Years assigned. Character in Register Book.

Diameter of Cylinder 38 x 40 Engines made at Kinghorn When made 1873
 Length of Stroke 48"
 Pressure of Steam 60lbs By whom made J Key
 Registered Horse Power 280HP

Particulars of Repairs and Examination This vessel was undergoing the requirements of Special Survey No: 1, and in accordance with the Society's Rules for Machinery & Boilers was examined by me. All the cocks &c forming sea connections are so arranged that it is not possible for water to be run into the vessel unintentionally. The other arrangements are in conformity with the requirements of the Rules, and the engines and boilers are in good working condition.

It is submitted that the vessel is eligible to have the notification Lloyd's No 11,77 recorded against her name in the Register Book and to be granted the usual Machinery Certificate.

Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.

The Surveyors are requested not to write on or below the space for Committee's Minute.

The Amount of Fee £ }
 Certificate (if required) £ } As per 187
 Travelling Expenses, if any, £ } Annexed form

William Parker
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute 15th January, 1878.
Lloyd's
W.W.

