

# ANNUAL SURVEYS.

No. 12 Survey held at London Date, first Survey 24 Dec<sup>r</sup> 1877 Last Survey 5 Jan<sup>r</sup> 1878 Rec. 9. 1. 78  
 No. in on the Bk Haddington Master  
 Reg. Book. 12 Tonnage 1206 Built at Liverpool When built 1846  
 By whom built Owners L. Young & Co  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Afloat with cargo on board

Last Survey, No. 19670 Port of London  
 Present Condition of the  
 Decks Good Treennails Rivets not  
 Waterways Dr Breasthooks and Stemson  
 Comings Dr Transoms, Pointers, and Crutches  
 Upper Deck Beams & Fastenings Dr Timbers of the Frame at the Openings how  
 Lower Deck Beams & Fastenings not seen Ditto ditto at other places seen  
 Planksheers Good Keelsons  
 Sheerstrakes Dr Clamps and Shelves  
 Topsides Dr Ceiling  
 Rudder Good  
 Copper or Y.M. Paint When put on 1877  
 Caulking of Bottom, Deck, & Waterways Good where seen  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Dr Cargo and Main Hatchways Good Hatches Dr  
 General Observations, Opinion as to Class, &c.

This vessel has put back in order to repair damage sustained through collision  
Bowport, jibboom and head gear generally, renewed - also figure - about  
15/10 main rail and bowport bits renewed - She is now in a good and  
efficient condition and eligible in my opinion to remain as classed

Committee's Minute 15th January, 1878.

Character assigned A

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 440 Survey held at London Date, first Survey 27 Dec<sup>r</sup> 1877 Last Survey 27 Dec<sup>r</sup> 1877 Rec. 9. 1. 78  
 No. in on the S. Glendarnel Master Pae  
 Reg. Book. 440 Tonnage 1761 Built at Glasgow When built 1870  
 By whom built Barclay Owners J & A. Allan  
 Port belonging to Glasgow Destined Voyage  
 If Surveyed Afloat or in Dry Dock Green's Lower Dock with ballast in hold

Last Survey, No. 17436 Port of London  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways Dr Breasthooks and Stemson  
 Comings Dr Transoms, Pointers, and Crutches  
 Upper Deck Beams & Fastenings Dr Timbers of the Frame at the Openings  
 Lower Deck Beams & Fastenings Dr Ditto ditto at other places where  
 Planksheers Dr Keelsons  
 Sheerstrakes Dr Clamps and Shelves  
 Topsides Dr Ceiling  
 Rudder Good  
 Copper or Y.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Dr Cargo and Main Hatchways Good Hatches Dr  
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and  
eligible in my opinion to remain as classed

Committee's Minute 15th January, 1878.

Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18