

1995

REPORT of SURVEY for REPAIRS, &c.

No. ¹⁴⁵ 1100 Survey held at Dublin Date, first Survey 6th Dec^r Last Survey 11 Dec^r 1877
on the SS Lord Byron Master Jones
Tonnage 515 built at Stockton When built 1865 7 mo
By whom built Richardson Owners Mess^{rs} Pelgrame Murphy
Port belonging to Dublin Destined Voyage Potterdam
If Surveyed Afloat or in Dry Dock In Dry dock

Last Survey, No. 1096-19281 Port Dublin 4th Sep^r 77 Classed SS Rpt No 3. 75
Years assigned. AI. 4-76
Character in Register Book. 9.74

REPAIRS, OR EXAMINATION AS PER RULE

Placed on blocks in Dry dock
On examination found the garboard plates & rivets from close aft to the extent of 24 feet forward started —
In the Fore end of the vessel a number of rivets in the Keel and Stem started or broken, but no other injury was apparent in any other part of the bottom

Repairs now done

24 ft Rivets to the extent of 24 feet along Keel and 3 feet up stem post all removed and renewed
Forward all started rivets removed & renewed
The parts where cement was removed renewed

In Survey 1096 Dublin 4th Sep^r 1877

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
General Observations, Opinion as to Class, &c.	Scuppers	Cargo and Main Hatchways
		Hatches

This vessel having now been thoroughly repaired I consider her to be in a good & efficient condition state of repair and in my opinion is fit to carry dry & perishable cargoes & from all parts of the world and is entitled to remain as classed in the Register Book

The Amount of Entry Fee ... £ 2 : 2 : received by me, APL

Surveyors fee Special ... £ 2 : 2 : 29/12 1877

Certificate (if required) ... £ 5 : 5 :
(Travelling Expenses, if any, £)

Committee's Minute 4th January, 1878

Character assigned APL

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

180N475-0380