

No. 38 Survey held at London Date, first Survey 30 Jan 1878 Last Survey 30 Jan 1878  
 No. in Reg. Book. on the S. Cartloch Master Phillips  
38 Tonnage 1264 Built at P. Glasgow When built 1874. 12 mo  
 By whom built Duncan Owners J. O. Hunter & Co<sup>rs</sup>  
 Port belonging to Greenock Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Greens Upper Dry Dock with ballast in hold



Last Survey, No. 185-18 Port of Glen Classed 100 A 1

Present Condition of the	Good	Treeails	Rivets	Good	Years assigned.	Character in Register Book.
Decks	<u>Good</u>					
Waterways	<u>Do</u>	Breasthooks and Stenson				
Comings	<u>Do</u>	Transoms, Pointers, and Crutches				
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the Openings				
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto ditto at other places		<u>when</u>		
Planksheers	<u>Do</u>	Keelsons				
Sheerstrakes	<u>Do</u>	Clamps and Shelves				
Topsides	<u>Do</u>	Ceiling		<u>seen</u>		
Wales	<u>Do</u>	Rudder		<u>Good</u>		
Plank (Bottom) and Counter	<u>Do</u>	Copper or <u>V.M.</u> Paint When put on <u>new</u>				
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.		Scuppers		<u>Do</u>		
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways		<u>Good</u>		
		Hatches		<u>Do</u>		

477

General Observations, Opinion as to Class, &c.  
*She now appears to be in a good and efficient condition and is eligible in my opinion to remain as classed*

Committee's Minute 12th February, 1878.

Character assigned 100A  
DPW

*J. Shear*

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

20185 I



© 2019

Lloyd's Register  
Foundation