

# ANNUAL SURVEYS.

20188  
 No. 397 Survey held at London Date 8 February 1878  
 on the Sew St Dornada Master Templeton  
 Tonnage 1943 Built at Dumbarton When built 1845-10ms  
 By whom built Denny Owners D. Macneil & P. Denny  
 Port belonging to Glasgow Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Shank Iron Works Dry Dock

Last Survey, No. 14374 Port of London Classed 100A 1 11.76

The present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson _____	} <u>where</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches _____		Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings _____		Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places _____		Sails <u>do</u>
Planksheers <u>do</u>	Keelsons _____		Anchors, No. of <u>3B - 1S - 2K</u>
Sheerstrakes <u>do</u>	Clamps and Shelves _____	Cables <u>Good where seen</u>	
Topsides <u>do</u>	Ceiling <u>seen</u>	Hawsers and Warps <u>Good &amp; sufficient</u>	
Wales <u>Plating</u>	Rudder <u>Good</u>	Standing and Running Rigging <u>Good</u>	
Plank (Bottom) and Counter <u>do</u>	Copper Paint When put on <u>now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*She now appears to be in a good and efficient condition and is eligible in my opinion to remain as classed*

Committee's Minute 1st March, 18 78.

Character assigned 100A 1

*Lloyd's Register*  
*Foundation*  
*My*  
*Heard*

180476-0129