

# ANNUAL SURVEYS.

No. 130

Survey held at

Calcutta

Date 30<sup>th</sup>

January

1878

on the

ship "British Consul"

Master

Atkinson

Tonnage

1267

Built at

Siverpool

When built

1866

By whom built

Rayden

Owners

British Ship Owners Coy Ltd

Port belonging to

Siverpool

Destined Voyage

Uncertain

If Surveyed Afloat or in Dry Dock

in dry Dock

Last Survey, No. 3

1873

Port of

London

Classed

\* A 1 at Lloyd's

The present Condition of the

Decks

good where seen

Treenails

Rivetting good where seen

Windlass and Capstan

good

Waterways

gutterings

"

Breasthooks and Stemsc

"

Pumps

"

Comings

"

Transoms, Point ss, and Crutches

"

Boats

satisfactory

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the Openings

"

Masts, Yards, &c.

"

Lower Deck Beams & Fastenings

"

Ditto Ditto at other places

"

Sails

2 good suits

Plank sheers

plating

"

Keelsous

"

Anchors, No. of

3 Bowers 1 Stream 2 Kedge

Sheerstrakes

"

"

Clamps and Shelves

"

Cables 300 fms lower 90 fms stream

Topsides

"

"

Ceiling

"

Hawsers and Warps

6 assorted

Wales

"

"

Rudder

good + well hung

Standing and Running Rigging all good

Plating (Bottom) and counter

"

Copper Paint When put on Jan 7 78

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

A strong well built iron vessel, has been docked for cleaning and painting bottom, and her rudder has been rebushed; recommend to be continued as classed.

Committee's Minute

26<sup>th</sup> February

18 78.

Character assigned

\* A 1

Wm Stewart & Co  
Surveyors to Lloyd's Register of S. & F. Shipping.

Port of Calcutta  
The 1 February 1878.

Certificate (if required.)

IRON 476 - 0440