

# REPORT of SURVEY for REPAIRS, &c.

No. 11912 Survey held at Sunderland Date, first Survey March 5<sup>th</sup> Last Survey March 19<sup>th</sup> 1878  
on the Sea Steamer "Hartlepool" Master H. G. Thompson

AGE under Tonnage Deck 538  
of Spar Deck, or Awning Deck  
of Poop  
of Raised Qr. Dk.  
of Houses on Deck  
of Forecastle  
Tonnage 557  
Space, as per Rule  
er Tonnage, cut on Beam  
e Room  
Tons as St<sup>r</sup>mer, cut on Bm. 415  
of Poop  
ft. Ditto, Forecastle  
18185  
Survey, No. 11613 Port Sunderland Iron  
Built at Sunderland When built 1865 - 10  
Owners E. J. Gourley Port belonging to Sunderland  
Residence Roker Terrace, Sunderland  
By whom built Laird Destined Voyage Coasting  
If Surveyed Afloat & in Dry Dock South graving dock  
ft. Years assigned. Character in Register Book.  
Classed 3.8.11 3.8.11

RS, OR EXAMINATION AS PER RULE S.S. No. 1

Now done, The vessel placed upon blocks in dry dock, and the  
bottom cleaned down and sighted; the limber boards and ceiling  
nailed to one strake fore & aft on each side removed, and both surfaces  
outside plating exposed; all the ceiling from the top of Ballast  
tanks removed, and the Man-hole doors in 8<sup>th</sup> removed. Several  
loose pieces stripped from the windlass and the chain cables ranged  
deck & found good & sufficient.

The Cement in the fore hold & in the Ballast tanks  
found to be adhering satisfactorily to the inner surface of the shell  
plating, the Cement being repaired in a few places where necessary;  
The outer surface of the shell plating scraped down, & re-coated with 2  
coats of black varnish up to the light marks, & 1 coat of paint above; the  
ceiling re-laid & repaired where necessary; the Hatches repaired and the  
Ballast tanks tested to a head of water above the Ballast marks  
Present Condition of the

Decks	Good	Fastenings	Good	Windlass and <sup>Winches</sup> Capstan	Good
Waterways	"	Breasthooks and Stems	"	Pumps Metal	
Comings	"	Transoms, Pointers, and Crutches	"	Boats 3 h <sup>ts</sup>	and
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c. Ex <sup>tr</sup> where	
Lower Deck Beams & Fastenings	and firm	Ditto Ditto at other places	"	Condition, how ascertained	Sufficient
Planksheers	Good	Keelsons	"	Sails	
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of 3 B. 15. 2 K	
Topsides	"	Ceiling	"	Cables 240 fath <sup>ms</sup> 1 1/2	
Wales	"	Rudder	"	Hawsers and Warps	
Plating (Bottom) and Counter	"	Copper Cement When put on 65, 67, 68, 74	"	Standing & Running Rigging	
Engine Room Skylights	Good	Caulking of	"		
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		

General Observations, Opinion as to Class, &c. This vessel is now in good & efficient  
State of repair, eligible in my opinion to remain as classed  
and to be marked in the Register Book S.S. No. 1-78

The Amount of Entry Fee ... £ : : received by me, } HN  
Special ... £ 4 : 4 : - 4 April 1878  
Certificate (if required) ... £ - : 5 : -  
(Travelling Expenses, if any, £ )

Committee's Minute

Character assigned

9th April 1878

S.S. No. 1-78

James Sibson  
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

IRON477-0032