

ANNUAL SURVEYS.

No. 3960 Survey held at West Hartlepool Date, first Survey 2 March Last Survey 4th March 1870
 No. in on the Sw. S. "Mary" Master H. Lawson
 Reg. Book. 1547 Tonnage 1048 Built at West Hartlepool When built 1871 4 mo
 By whom built Bentley Owners Johnston & Co
 Port belonging to Montrose Destined Voyage
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 14969 Port of Leam

Present Condition of the Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings Good

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes Good

Topsides "

Wales "

Plank (Bottom) and Counter Good

Engine Room Skylights Good

General Observations, Opinion as to Class, &c.

Treenails Good

Breasthooks and Stemson Good

Transoms, Pointers, and Crutches Good

Timbers of the Frame at the Openings Good

Ditto ditto at other places Good

Keelsons Good

Clamps and Shelves Good

Ceiling Good

Rudder Good

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways Good

Coal Bunker, Openings, Lids, &c. Good

Scuppers Good

Cargo and Main Hatchways Good

Hatches Good

Windlass and Capstan Good

Pumps Two & Good

Boats Four & Good

Masts, Yards, &c. Good

Condition, how ascertained From Deck

Sails Good

Anchors, No. of 3 Buoys (Steam, 2 Red)

Cables Good

Hawsers and Warps 7/2 - 11 - 8 - 7/2 - 7 - 6/2 - 6 in Good

Standing and Running Rigging Good

General Observations, Opinion as to Class, &c. Now done Bottom cleaned down & coated with paint & black barnish

Is now in a good & efficient state & is fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now

Classed 90 A1

S. S. H. (No 1-75)

Committee's Minute

8th March, 1878.

Character assigned

90 A1

TSW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of

Classed

Present Condition of the Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways

Coal Bunkers, Openings, Lids, &c. Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations, Opinion as to Class, &c.

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18