

ANNUAL SURVEYS.

285-88

Rec 1/4/78

No. 4637 Survey held at Shull Date, first Survey 17 March Last Survey 22 March 1878
 on the Iron Ship "Dean Ray" Master A. Horn
 Tonnage 1068 1/2 Built at Glasgow When built 1876
 By whom built Jobie Owners Halford & Cameron Esq
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In dry dock & afloat

Last Survey, No. 14468 Port of Leam
 Present Condition of the Decks Good Keels When run Good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do Windlass and Capstan
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do Pumps
 Lower Deck Beams & Fastenings do Ditto ditto at other places do do Boats
 Planksheers do Keelsons do do Masts, Yards, &c.
 Sheerstrakes do Clamps and Shelves _____ Condition, how ascertained
 Topsides do Ceiling do do Sails
 Wales do Rudder do do Anchors, No. of
 Plank (Bottom) and Counter do Copper or Y.M. _____ When put on _____ Cables
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. None done

Classed _____ Years assigned _____ Character in Register Book 100-A-1
12.46

Is eligible in my opinion to remain as classed.

Committee's Minute 2nd April, 1878.
 Character assigned 100A-1
DBW

James M Neil
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at Shull Date, first Survey 18 March Last Survey 23 March 1878
 on the Iron Ship "Albanian" Master Sinclair
 Tonnage 1340 1/2 Built at Glasgow When built 1855
 By whom built _____ Owners Wm Horn, Atkinson Esq
 Port belonging to Shull Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On Slipway & afloat

Last Survey, No. 19192 Port of Leam
 Present Condition of the Decks Good Keels When run Good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do Windlass and Capstan
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do Pumps
 Lower Deck Beams & Fastenings do Ditto ditto at other places do do Boats
 Planksheers do Keelsons do do Masts, Yards, &c.
 Sheerstrakes do Clamps and Shelves _____ Condition, how ascertained
 Topsides do Ceiling do do Sails
 Wales do Rudder do do Anchors, No. of
 Plank (Bottom) and Counter do Copper or Y.M. _____ When put on _____ Cables
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. None done

Classed _____ Years assigned _____ Character in Register Book 90-A-1
11.76-4.44

The bottom cleaned and painted; also two slightly damaged hull plates repaired.
Is eligible in my opinion to remain as classed.

Committee's Minute 2nd April, 1878.
 Character assigned 90A-1
DBW

James M Neil
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____